

Thank you for purchasing a Sealey Product. Manufactured to a high standard this tool will, if used according to these instructions and properly maintained, give years of trouble free performance.

▲ IMPORTANT: PLEASE READ THESE INSTRUCTIONS CAREFULLY. NOTE THE SAFE OPERATIONAL REQUIREMENTS, WARNINGS AND CAUTIONS. USE THIS PRODUCT CORRECTLY AND WITH CARE FOR THE PURPOSE FOR WHICH IT IS INTENDED. FAILURE TO DO SO MAY CAUSE DAMAGE AND/OR PERSONAL INJURY AND WILL INVALIDATE THE WARRANTY. PLEASE KEEP INSTRUCTIONS SAFE FOR FUTURE USE.

1. SAFETY INSTRUCTIONS

- ❑ **WARNING!** Ensure Health & Safety, local authority and general workshop practice regulations are adhered to when using the torch.
- ✓ Familiarise yourself with the applications, limitations and potential hazards of the tool.
- ✓ Replace or repair damaged parts. Use genuine parts only. Unauthorised parts may be dangerous and will invalidate the warranty.
- ✗ **DO NOT** repair the torch yourself, use an authorised service agent.
- ❑ **WARNING!** Use and handle the butane gas (lighter fuel) in accordance with any instructions supplied with the fuel.
- ✓ Butane gas is highly flammable, so keep an appropriate fire extinguisher at hand.
- ✓ Ensure that there are no flammable or combustible materials near the work area.
- ✓ Keep the work area clean and uncluttered and ensure that there is adequate ventilation and lighting.
- ✓ Keep children and unauthorised persons away from the work area.
- ✓ Remove ill fitting clothing. Remove ties, watches, rings and other loose jewellery and contain and/or tie back long hair.
- ✓ Point the torch away from yourself and others when igniting flame.
- ✓ Keep hands and body clear of the torch head when operating as it becomes very hot.
- ✓ Secure unstable workpiece with a clamp, vice or other adequate holding device.
- ✓ Always use the integral stand when the torch is not in use.
- ✗ **DO NOT** get the torch wet.
- ✗ **DO NOT** use torch where there are flammable liquids, solids or gases such as paint solvents and including waste wiping or cleaning rags etc.
- ✗ **DO NOT** use the torch for any purpose other than that for which it is designed.
- ✗ **DO NOT** use accessories other than those supplied with, or manufactured specifically for use with, the torch.
- ❑ **WARNING! DO NOT** touch the torch head during, or immediately after, use. Allow the torch to cool naturally before handling.
- ✗ **DO NOT** cool the torch in water.
- ✗ **DO NOT** point the torch at yourself, others, or animals.
- ✗ **DO NOT** operate the torch when you are tired or under the influence of alcohol, drugs or intoxicating medication.
- ✗ **DO NOT** allow untrained persons to operate the torch.
- ✗ **DO NOT** operate the torch if any parts are damaged or missing as this may cause failure and/or personal injury.
- ✗ **DO NOT** touch the workpiece close to the heated area as it will be very hot. Allow to cool.
- ✗ **DO NOT** leave the torch after use, until it has cooled.
- ✓ When work is complete, allow the torch to cool. Clean the torch and accessories and store in a safe, dry childproof location.
- ✗ **DO NOT** store in direct sunlight or where the temperature could exceed 104°F/40°C
- ❑ **WARNING!** Failure to use the torch correctly may result in fire, damage and/or personal injury.
- ▲ **DANGER! The flame is invisible in sunlight - be extremely cautious.**

2. INTRODUCTION

The AK2951 torch is portable and lightweight, suitable for heating and soldering. Powered by butane gas (lighter fuel), the torch has slide switch ignition and automatic flame selection for quick and clean operation.

AK2951 Set comprises: Torch, Hot Air Nozzle, Soldering Tip, Safety Cap.



3. OPERATING INSTRUCTIONS

- ❑ **WARNING!** Ensure you have read and understood the safety instructions in Section 1 before using the torch.

Note: The torch is supplied without butane gas. Before use it must be fuelled as follows:

3.1. TO FUEL THE TORCH

- 3.1.1. Use only high quality butane gas (lighter fuel) to fill the torch.
- 3.1.2. Ensure the "On/Off" switch is in the "Off" position. See fig. 1, "On/Off" Safety Switch.
- 3.1.3. Follow the instructions on the butane fuel can.
- 3.1.4. Apply the can filler tip to the torch base filler valve (figs. 1 & 2). Use a pumping action for best filling results.
- 3.1.5. Once full, allow gas in the torch to stand and stabilise for a few minutes before use.



3.2. TO USE AS A SOLDERING IRON

▲ CAUTION: ENSURE ALL PARTS ARE COOL FROM ANY PREVIOUS USE BEFORE PROCEEDING.

- 3.2.1. Screw the soldering tip, into the threaded hot air nozzle (fig. 1).
- 3.2.2. Screw the nozzle onto the torch burner head (fig. 1) as far as it will go.
- 3.2.3. Turn "On/Off" safety switch to "On" position and move flame control (fig. 1) towards "+" until the gas can just be heard hissing.
- 3.2.4. To ignite the flame, slide the ignition switch (fig. 1) forward until a sharp click is heard. Hold switch in this position for approximately two seconds after ignition.
- 3.2.5. Allow the ceramic element inside the nozzle to heat up for about five seconds. Observe the element through the air hole (fig. 1.A), it should glow red.
- 3.2.6. Turn the flame control (fig. 1) to adjust the gas flow to the minimum which will sustain the ceramic glow.
- 3.2.7. Allow the torch to stand for about 2 minutes in order to achieve maximum output.

Note: *If you cease working and intend to restart, allow all parts to cool before following above procedure again.*

3.3. TO USE FOR HEATING

- 3.3.1. Remove the soldering tip from the hot air nozzle.
- 3.3.2. Screw the hot air nozzle onto the torch burner head.
- 3.3.3. For ignition follow steps 3.2.3. to 3.2.7. above. The torch is now ready for use as a heat source.

3.4. TO USE AS A BURNER (with naked blue flame for burning or heating)

- 3.4.1. Remove the nozzle from the torch. No attachments are required for this mode.
- 3.4.2. Ignite the torch as in 3.2.3. to 3.2.4. above.
- 3.4.3. Adjust the flame with the flame control (fig. 1). Recommended flame length 10 - 25mm.
- 3.4.4. Apply flame to task accordingly. Only use the minimum flame necessary. Too large a flame is less stable and will waste fuel.

3.5. TURNING OFF THE TORCH

- 3.5.1. When the job is complete move the flame control fully to " - " and the "On/Off" switch to "Off".
- 3.5.2. Cover the head of the torch with the transparent safety cap to prevent accidental burning/melting of people or materials.

☐ **WARNING!** The hot air nozzle and soldering bit, if fitted, will be very hot. Allow to cool before handling.

3.6. GENERAL INFORMATION

- 1) Approximate operating time on one gas filling (8ml) - 40 minutes.
- 2) Keep the torch clean and store safely in case provided.
- 3) For spare soldering/heating tips and parts contact your local Sealey dealer.

4. TROUBLESHOOTING






The torch will not ignite.	No fuel. Too high or too low gas pressure. Air holes blocked. Damaged torch/piezo fault.	Refill with butane gas. Adjust the flame control. Check that all holes are clear. Contact Service Agent/ignite with external flame.
Tip does not heat up.	Ceramic element is worn or damaged. Poor gas pressure.	Replace. Re-fill with gas or allow cold gas to warm up - shake gently to assist warming.

NOTE: It is our policy to continually improve products and as such we reserve the right to alter data, specifications and component parts without prior notice.

IMPORTANT: No liability is accepted for incorrect use of this product.

WARRANTY: Guarantee is 12 months from purchase date, proof of which will be required for any claim.

INFORMATION: For a copy of our catalogue and promotions call us on 01284 757525 and leave your full name and address, including postcode.

	Sole UK Distributor, Sealey Group, Bury St. Edmunds, Suffolk.		
 01284 757500	 01284 703534	 sales@sealey.co.uk	 www.sealey.co.uk