



# WORKSHOP WELDING CURTAINS

## TO EN ISO 25980:2014

### MODEL NO: SSP99.V2, SSP992, SSP993

Thank you for purchasing a Sealey product. Manufactured to a high standard, this product will, if used according to these instructions, and properly maintained, give you years of trouble free performance.

**IMPORTANT:** PLEASE READ THESE INSTRUCTIONS CAREFULLY. NOTE THE SAFE OPERATIONAL REQUIREMENTS, WARNINGS & CAUTIONS. USE THE PRODUCT CORRECTLY AND WITH CARE FOR THE PURPOSE FOR WHICH IT IS INTENDED. FAILURE TO DO SO MAY CAUSE DAMAGE AND/OR PERSONAL INJURY AND WILL INVALIDATE THE WARRANTY. KEEP THESE INSTRUCTIONS SAFE FOR FUTURE USE.



Refer to instruction manual

## 1. SAFETY

- WARNING!** Ensure Health & Safety, local authority and general workshop practice regulations are adhered to when using this equipment.
- Familiarise yourself with the application and limitations of the curtain, as well as the specific potential hazards.
- Maintain the curtain in good condition (use an authorised service agent).
- Replace or repair damaged parts. Use genuine parts only. Non-authorized parts may be dangerous and will invalidate the warranty.
- Keep the work area clean and uncluttered and ensure there is adequate lighting.
- Keep the curtain clean for best and safest performance.
- Keep children and unauthorised persons away from the work area.
- DO NOT** use the curtain for any purpose other than that for which it is designed.
- DO NOT** use the curtain if any parts are damaged or missing as this may cause failure and/or personal injury.

## 2. INTRODUCTION

Amber welding screen manufactured to EN ISO 25980:2014. Suitable for use in workshops where the glare from welding and cutting may be a hazard to others. Curtain and frame supplied flat-packed, but assembles with ease.

## 3. SPECIFICATION

Model:	SSP99.V2	SSP992	SSP993
Width:	1.3m	1.8m	2.4m
Height:	1.75m	1.75m	1.75m

## 4. ASSEMBLY

- 4.1. Take the two lower corner frame fittings (fig.2B) and insert them into the two feet. (fig.2E)
- 4.2. Insert the bottom horizontal bar (fig.2D) between the two feet (fig.2E), ensure that the sprung catches are seated correctly.
- 4.3. Insert the long vertical bars (fig.2C) in to the top of the corner fittings, ensure that the sprung catches are seated correctly.
- 4.4. Connect the two upper corner fittings (fig.2A) to the two vertical bars and then the remaining top bar (fig.2D) to them. Ensure that the sprung catches are seated correctly.
- 4.5. Stand the frame up and make sure the feet are square.
- 4.6. Take the welding curtain and with it the correct way around secure it to the frame with the ties
- 4.7. The frame can be raised or lowered by loosening the thumb screw (fig.1) on the feet, when at the required height, tighten the thumb screw.




fig.1




fig.2



### ENVIRONMENT PROTECTION

Recycle unwanted materials instead of disposing of them as waste. All tools, accessories and packaging should be sorted, taken to a recycling centre and disposed of in a manner which is compatible with the environment. When the product becomes completely unserviceable and requires disposal, drain any fluids (if applicable) into approved containers and dispose of the product and fluids according to local regulations.

**Note:** It is our policy to continually improve products and as such we reserve the right to alter data, specifications and component parts without prior notice. Please note that other versions of this product are available. If you require documentation for alternative versions, please email or call our technical team on technical@sealey.co.uk or 01284 757505.

**Important:** No Liability is accepted for incorrect use of this product.

**Warranty:** Guarantee is 12 months from purchase date, proof of which is required for any claim.

Sealey Group, Kempson Way, Suffolk Business Park, Bury St Edmunds, Suffolk. IP32 7AR

01284 757500

01284 703534

sales@sealey.co.uk

www.sealey.co.uk