



**ELENCO PEZZI DI RICAMBIO
 LISTE PIECES DETACHEES
 SPARE PARTS LIST
 ERSATZTEILLISTE
 PIEZAS DE REPUESTO**

SUPERSTART 310

Explosio macchina, Dessin appareil, Machine drawing, Explosions Zeichnung des Geräts, Diseño seccionado maquina.



Original Date: 27/8/97
 Issue Date: 27/8/97
 Version Number: 1
 Date Modified:



REF.	ELENCO PEZZI DI RICAMBIO PIECES DETACHEES SPARE PARTS LIST ERSATZTEILLISTE PIEZAS DE REPUESTO	CODICE	CODE	KODE
1	Raddrizzatore Redresseur Rectifier Gleichrichter Rectificador	112200		
2	Termostato Thermostat Thermostat Thermostat Termostato	122308		
3	Interruttore Interrupteur Switch Schalter Interruptor	122381		
4	Deviatore Gareur Switch Schalter Interruptor	122400		
5	Cavo Di Carica Positivo Cable Charge Positive Cable For Positive Charge Positiv Kable Cable De Carga	123113		
6	Cavo Alimentazione Cable De Reseau Mains Cable Netzkabel Cable Alimentador	132193		
7	Amperometro Amperetre Ammeter Amperemeter Amperometre	152133		
8	Trasformatore Transformateur Transformer Transformator Transformador	164120		
9	Volantino Volant Handwheel Handrad Voiante	312052		
10	Pressacavo Presse Cable Cable Bushing Kabelhalter Prensa Cable	322008		
11	Ruota Roue Wheel Rad Rueda	322193		
12	Asse Per Ruote Axe Pour Roue Wheels Axle Raederachse Eje Por Rueda	422961		

REF.	ELENCO PEZZI DI RICAMBIO PIECES DETACHEES SPARE PARTS LIST ERSATZTEILLISTE PIEZAS DE REPUESTO	CODICE	CODE	KODE
13	Fondalino Chassis Bottom Boden Fondo	644177		
14	Manico Poignee Handle Handgriff Manija	645076		
15	Piede Embout Foot Fuss Pie	644422		
16	Cruscotto Plaque Dash Board Stirnwand Tablero	647671		
17	Retro Partie Arriere Back Part Rueckseite Parte Trasera	650098		
18	Frontale Partie Frontale Front Panel Stirnseite Frontal	650982		
19	Cavo Massa Cable De Masse Work Cable Massekabel Cable De Masa	713199		
20	Kit 20 Fusibili Kit 20 Fusible Kit 20 Fuse Kit 20 Sicherung Kit 20 Fusible	802259		
21	Pinza Di Massa Pince De Masse Work Clamp Masseklemme Pinza De Masa	990085		
22	Pinza Di Carica Pince De Charge Pincer For Charging Ladungszange Pinzas De Carga	990086		
23	Morsetto Completo Borne Complete Complete Clamp Komplett Klemme Borne Completo	990162		
24	Coppia Rondelle Isolanti Rondelles Isolantes Couple Of Insulating Washers Isolierscheibepaar Par De Arandelas Asladoras	990163		

Schema elettrico, Schéma électrique, Diagram, Schaltplan, Esquema de conexiones

