


Parts Information:

Air Conditioning Leak Detection Kit Model No: VS600



Item	Part No.	Description
1	153.238F011	Cable Fastener & Dowel
2	153.238T004	Bulb Socket
3	153.238TD001	Dichroic UV Bulb, 50W, 12V, Halogen Osarm
4	153.30400002	Push Button Switch
5	153.30400004	Glass Filter
6	153.30400005	Clamp, Red
7	153.30400006	Clamp, Black
8	153.30400007	O-Ring Seal
9	153.304007	Spring
10	153.30400020	Self Tapping Screw Din7982 3.9x13mm

Item	Part No.	Description
11	153.30400008	Injector Complete
12	153.30400023	Goggles
13	VS60012	Air Conditioning Fluorescing Leak Detection Dye - 12 Doses
	VS60033	Air Conditioning Fluorescing Leak Detection Dye - 33 Dose Bo (NOT SHOWN)
14	153.304001403	Lamp Body, Black
15	153.304001404	Lamp Cover, Grey
17	153.304001	Rotating Coupling 6/4
18	153.304002	Rotating Coupling 4/6
	153.30400000	Complete Lamp (NOT SHOWN)

NOTE: It is our policy to continually improve products and as such we reserve the right to alter data, specifications and component parts without prior notice. IMPORTANT: No liability is accepted for incorrect use of product.

WARRANTY: Guarantee is 12 months from purchase date, proof of which will be required for any claim.

Sealey Group, Kempson Way, Suffolk Business Park, Bury St Edmunds, Suffolk. IP32 7AR



01284 757500



01284 703534



sales@sealey.co.uk



www.sealey.co.uk

VS600 Issue 2 DPL 21/06/18 Page 1 of 1