


COMBI 651 - SPARE PARTS DIAGRAM

v1.0 04/2003



COMBI 651 - SPARE PARTS LIST			v1.0 04/2003
No.	Qty.	Desc.	Ref.
1	1	Combi 651 Jig	COMBI/651
2	3	Alloy Bush	CJ/BUSH
3	1	Length Setting Stop	CJ/LSK
4	0	Machine Screw Csk M8 x 50mm Slot	WP-SCW/41
5	0	Washer 8.5mm x 32mm x 1.0mm	WP-WASH/17
6	0	Knob M8	WP-KNOB/10
7	0	Combi Jig 'O' Ring Pack for Bushes (pack of 5)	CJ/ORS
8	1	Manual	MANU/651